



Dustite® combines a loose wheel nut Indicator, with a standard dust cap for use on wheels without trims. Like the Checkpoint®, Dustites® indicate loosening of safety critical nuts and includes a wheel overheating function, but offers the additional benefits that come with a wheel nut cap for protecting the nut from weathering, corrosion and general road damage. The Dustite® indicator is a core product from Checkpoint Safety and is in high demand globally to include specifications of the product for Western Europe, North America, Asia, Australasia, Sub Saharan Africa and South America with increasing sales in Eastern Europe and Northern Africa. The Dustite® covers a wide scope of applications throughout industrial, agricultural, military and commercial vehicle sectors amongst others.



The primary functions of Dustites® are to:


- ✓ Provide a clear visual indication of nut movement, particularly useful and applicable for commercial vehicle wheels
- ✓ Provide an indication of wheel overheating which is otherwise difficult to detect, usually as a result of brakes sticking or problems with the bearings
- ✓ Provide a clear visual commitment to roadworthiness and professionalism to other road users and transportation associations such as DFT, VOSA and FTA
- ✓ Prolong the service life of studs/nuts by protecting from corrosion/weathering



The primary benefits of fitting Dustites® are:

- ✓ Improved safety of fittings where nuts are a critical structural component, such as on vehicle wheels, rail track and industrial/commercial structures
- ✓ Facilitates the ease of walk around and visual checks/audits to locate problems
- ✓ Reduced maintenance time/costs resulting from accurate locating of nut loosening or wheel overheating
- ✓ Reduction in vehicle downtime
- ✓ Improved safety and protection of nuts/bolts from corrosion & damage
- ✓ Improved professionalism, roadworthiness and company image/reputation
- ✓ Low cost, quick and easy solution to implement

Dustite
Nut movement indicator
Product: with protective nut cap



Available* sizes

*Measured across flats of the nut. Stock levels can vary, depending on size and colour

Standard Colours

Fluoro
Yellow

Red

Other available* Colours

*Subject to stock and/or minimum order quantity

Silver
Grey

Black

Drab Olive
Grey


Blue

Green

Orange

White

Solid
Yellow



UHT 203 °C

HT 165 °C

Standard 124 °C

High Temp (HT) and Ultra High Temp (UHT) melting point options available with minimum order quantity. Dustite LR® info available on request.